

Numericals related \bar{x} , R, c & p-charts

1) calculate the upper ^{and lower} control limits for the p-chart given the following data, when $n=100$

(20, 10, 15, 18, 19, 20, 17, 16, 14, 29, 16, 17)

Solution

For p-chart upper and lower control limits are

$$\bar{p} \pm 3 \sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$$

$$\text{i.e. upper control limits} = \bar{p} + 3 \sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$$

$$\text{Lower control limit} = \bar{p} - 3 \sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$$

$$\bar{p} = \frac{\sum_{i=1}^k \hat{p}_i}{k} = \frac{(20+10+15+18+19+20+17+16+14+29+16+17)}{12}$$

$$\bar{p} = \frac{211}{12} = \frac{2.11}{12}$$

$$\bar{p} = 0.1758$$

$$\begin{aligned} & \bar{p} \pm 3 \sqrt{\frac{\bar{p}(1-\bar{p})}{n}} \\ & = 0.1758 \pm 3 \sqrt{\frac{0.1758(1-0.1758)}{100}} \\ & = 0.1758 \pm 0.1142 \end{aligned}$$

So Upper control limits = $0.1758 + 0.1142$
 (UCL) = 0.2900

Lower control limit = $0.1758 - 0.1142$
 (LCL) = 0.0616

* Numerical problem based on control chart
 \bar{X} & R

The following data was obtained
 (Table, no. 1) for diameter of a component
 from shop floor: construct \bar{X} & R charts.

Find control limits for sample size '5'
 take

$A_2 = 0.577, D_4 = 2.114, D_3 = 0$

Sample No	\bar{X}	R
1	50.04	0.07
2	50.24	0.08
3	50.14	0.03
4	50.08	0.05
5	50.28	0.04
6	50.16	0.08
7	50.30	0.04
8	50.10	0.03
9	50.16	0.06
10	50.10	0.07

Solution calculate $\bar{\bar{X}}$ & \bar{R}

$$\text{Grand average } \bar{\bar{X}} = \frac{\sum \bar{X}}{N}$$

$$= \frac{(50.04 + 50.24 + 50.14 + 50.08 + 50.28 + 50.16 + 50.30 + 50.10 + 50.16 + 50.10)}{10}$$

$$\therefore \bar{\bar{X}} = 50.16$$

$$\text{Range average } \bar{R} = \frac{\sum R}{N}$$

$$= \frac{(0.07 + 0.08 + 0.03 + 0.05 + 0.04 + 0.08 + 0.04 + 0.03 + 0.06 + 0.07)}{10}$$

$$\therefore \bar{R} = 0.055$$

Now the control limits for \bar{X} chart

$$\text{upper control limit (UCL)} \bar{X} = \bar{\bar{X}} + A_2 \bar{R}$$

$$\therefore \text{UCL } \bar{X} = \bar{\bar{X}} + A_2 \bar{R}$$

$$= 50.16 + (0.577 \times 0.055)$$

$$\therefore \text{UCL } \bar{X} = 50.19$$

Lower control limit (LCL) $\bar{x} = \bar{x} - A_2 \bar{R}$

$= 50.16 - 0.577 \times 0.055$

$\therefore \boxed{LCL \bar{x} = 50.12}$

New control limits for R chart

Upper control limit (UCL) $R = D_4 \bar{R}$

Lower control limit (LCL) $R = D_3 \bar{R}$

$UCLR = D_4 \bar{R}$

$= 2.114 \times 0.055$

$\therefore \boxed{UCLR = 0.1162}$


$LCLR = D_3 \bar{R}$

$= 0 \times 0.055$

~~$LCLR = 0$~~
 $\therefore \boxed{LCLR = 0}$

Now we will control constant of \bar{x} chart


\bar{x} chart



Sample No. →

AS some points like Sample No 1, 4, 8 & 10 falls below Lower control limits and sample no. 2, 5, and 7 being above upper control limit, so process is not in control.

R chart



Sample No. →

AS in R charts all points falls in between two limits i.e. ucl and L.C.L. so for large value the process is in control.

Numerical on c-chart

Ten castings were inspected in order to locate defects in them. Every casting was found to contain certain number of defects as given below. It is required to plot a c-chart and draw conclusion.

<u>Castings</u>	<u>No. of defects found on inspection (c)</u>
1	2
2	4
3	1
4	5
5	5
6	6
7	3
8	4
9	0
10	7
<u>Total</u> 10	<u>37</u>

$$\therefore \bar{c} = \frac{37}{10} = 3.7$$

$$UCL = \bar{c} + 3\sqrt{\bar{c}}$$


$$LCL = \bar{c} - 3\sqrt{\bar{c}}$$

$$\text{or } UCL = 3.7 + 3\sqrt{3.7} \\ = 9.472$$

$$LCL = 3.7 - 3\sqrt{3.7}$$

$= -2.072 = \text{zero}$ AS LCL is -ve so it has been taken as being zero.

C-chart



It is concluded that since all the values of C are within the control limits, the process is under control.